




Part # 12119400 - 67-70 Cougar Billet Tie Rod Adjuster

Recommended Tools



Major ComponentsIn the box

| QTY | Part Number | Description |
|-----|-------------|--------------------------------|
| 2 | 90000138 | Tie Rod Adjuster |
| 2 | 99800000 | 1 1/16" -18 Right Hand Jam Nut |
| 2 | 99800001 | 1 1/16" -18 Left Hand Jam Nut |

NOTES:

This Tie Rod Adjuster is designed to take place of the OEM steel sleeve.

One end of the adjuster has a **groove** cut in it, this is the **LEFT HAND** threaded side.

When installing the Tie Rod Adjuster, use antisieze compound on the threads.

FOR YOUR SAFETY, THE TIE RODS NEED A MINIMUM 1 1/32" OF THREAD ENGAGEMENT INTO THE TIE ROD ADJUSTER. USE THE SIGHT HOLE IN THE SIDE OF THE TIE ROD ADJUSTER TO ENSURE PROPER THREAD ENGAGEMENT.

